


PASS THE CLEAR 3 CORE SUPPLY CABLE AND THE 4 SUPPORT WIRES THROUGH THE CEILING PLATE AS ILLUSTRATED








PASS THE CLEAR 3 CORE SUPPLY CABLE THROUGH THE FIGURE 8


WIRE THE 3 CORE SUPPLY CABLE TO THE TERMINAL BLOCK AS ILLUSTRATED



PASS THE 4 SUPPORT WIRES THROUGH THE METAL STOPS AND LOCK THEM IN PLACE USING THE ALLEN KEY AND GURB SCREWS AS ILLUSTRATED



A	B	C
122PCS	514PCS	72PCS



MAINS SUPPLY



LIGHT FITTING

APPROVED
10/5/2023
ISSUE 2

Q.C