

searchlight

36130

CE UK EAC

1

8

2

3

4

5

6

7

MAINS SUPPLY

LIVE - Possible colours : Red or Brown

EARTH - Un sleeved copper or (Green / Yellow)

NEUTRAL - Possible colours : Black or Blue

LIGHT FITTING

LIVE

EARTH

NEUTRAL

IP44

Q.C. APPROVED
10/06/2024
ISSUE 1

OUTDOOR LUMINARIES

Stainless steel/aluminium enjoys a strong and enduring reputation for long term appearance and structural integrity. But like all materials they may become stained or discoloured over time, impairing the overall look. This brown discoloration is referred to as “tea staining”. Tea staining can be defined as: Discoloration of the surface of stainless steel/aluminium that does not affect the structural integrity or the longevity of the material.

CONTRIBUTING FACTORS:

The relationships between the contributing factors are complex, but generally become increasingly critical closer to marine environments.

ENVIRONMENTAL FACTORS:

Tea staining occurs most commonly within 5 miles of the sea and becomes progressively worse closer to the marine source. However, wind exposure, pollution levels and higher temperatures can create environments where tea staining may occur outside the 5 mile limit. Therefore we recommend not to place this product within 5 miles of the sea/estuary.

MAINTENANCE:

As with most outdoor products occasional maintenance is required to ensure protection from the elements. We would advise that fine grade oil (Such as ‘Baby Oil’ or WD40) is rubbed into the metal sections of the product. Regular treatment should aid the life and appearance of the product.

GUARANTEE:

We will not assume responsibility for corrosion or any other resulting damage to our products where they are installed in areas in which fertilizers or salt are present, either in the air or in the soil, or where our products are installed near to chemical plants etc. with emissions of heavily polluted air.

LED Outdoor Luminaires

Special Note.

Please note that condensation may occur in this product.

This is because LED bulbs run cooler than a normal incandescent bulb.

This is not a fault and will dissipate in time.

Q1002