



MAINS SUPPLY

LIGHT FITTING



If required the fitting can be lengthened back to its original height



2. Push the 2 small metal release pins in individually, this will release the clamp and allow each support wire to become free to lengthen.

.The weight of the fitting is normally sufficient to lower each support wire, however should the cable not move freely, gently hold the support wire whilst the pushing and the release pin and pull down on the cable.